

Public Works Department / Buildings Organization

From

Er.A.Valluvan,B.E.,M.E.(Struct),
Superintending Engineer, PWD,
Buildings (C&M) Circle, Trichy-1
Phone : 04312462604,
Email:sebuildings_trichy@yahoo.com

To

The Chief Executive Officer,
CARE International School,
No. #27,, Thayanur,
Trichy - 620 009.

Letter No. F-14/DB/DO-1 /2022/Date: 18.08.2022


Sir,


Sub: Buildings – Structural Stability Certificate for **CARE International School, #27, Thayanur, Trichy - Structural Stability issued- - reg.**

- Ref: 1. The Chief Executive Officer, **CARE International School, #27, Thayanur, Trichy** District application
Lr. Nil Date:11.05.2022.
2. The Chief Engineer (Buildings) PWD, Trichy Region,
Trichy-20, Lr.No. / AEET1 / F.Stability / 2022/
Dated: 12.08.2022.

With reference to the above letter cited, I enclose herewith the Structural Stability Certificate for **CARE International School, #27, Thayanur, Trichy** for taking further action.

Encl: Structural Stability Certificate.


Superintending Engineer, PWD,
Buildings (C&M) Circle, Trichy-1



18/8/2022


OFFICE OF THE SUPERINTENDING ENGINEER, PWD.,
BUILDINGS CONSTRUCTION & MAINTENANCE CIRCLE, TRICHY-1.

FROM E

From of report to be made to the competent Authority be inspecting authorities or officers appointed under section 28 of the Madras Public (Licensing) Act 1965 (Madras Act 13 of 1965) referred in rule 7 of the Madras Public Buildings (Licensing) Rule 1966

1	Name of the Designation of Inspecting authority or officer appointed or having jurisdiction under any other act of Law	Er.A.Valluvan,B.E.,M.E.(Struct), Superintending Engineer, PWD Building (C&M) Circle, Trichy-1. "
2	Location of the building inspected (Door No Street No Name. of Place i.e Municipal corporation / Municipality / Panchayat or Panchayat Union / Township / Contonment	CARE International School, Door No. #27, SF.No.9/8, 9/9, 9/10, 2/2, A1G & 2/2 A1H Thayanur, Trichy
3	Date of Inspection	15.06.2022
4	Purpose for which the building is used	Education (School Building)
5	Nature of defects noticed	NIL
6	Suggestions for rectifying defects	NIL
7	If in a dangerous condition immediate steps recommended to be taken	NIL


Superintending Engineer, PWD,
Buildings (C&M) Circle, Trichy-1


18/8/2022

OFFICE OF THE SUPERINTENDING ENGINEER, PWD, BUILDINGS
CONSTRUCTION AND MAINTENANCE CIRCLE, TRICHY.1.


Form of opinion under sub section (1) of section 5 of the Madras Public Building (Licensing) Act 1965 (Madras Act 13 of the 1965 referred to in rule 5 of th Madras Public buildings (Licensing) Rules 1966)


I have inspected the building specified in the statement below assuming that the building has been completed under the supervision of private chartered engineer as per the design furnished by Er.R.Vetrivel, M.Tech (Structural), F.I.V.,C.E.(I) I am of the opinion that the building is structurally sound to be used as a Public Building for the purpose specified in the statement subject to the following conditions.

- 1) The building is designed for GF+2 Floors only and it has been completed.
- 2) The structural stability of the structure has been assessed based on the foundation details and soil report produced by the owner of the building.
- 3) Any alterations and additional buildings should not be carried out in the existing building (as per approved plan)

The structural soundness of the building has been verified based on the foundation details given by the owner and loading conditions as per the latest Indian Standards 875. I am therefore of the opinion that a license may be granted for the period from 07.06.2022 to 06.06.2025

Date of Inspection: 15.06.2022


Superintending/ Engineer., P.W.D.,
Buildings (C&M) Circle, Trichy-1.


18/8/2022

**OFFICE OF THE SUPERINTENDING ENGINEER, PWD,
BUILDINGS CONSTRUCTION & MAINTENANCE CIRCLE, TRICHY**

From of opinion under sub-section (1) of section 28 of the Madras Public Building (Licensing) ACT 1965 (Madras ACT 13 of the 1965 referred to in rule 7 of the Madras Public building (Licensing) Rules 1966)

I have inspected the building specified in the statement below assuming the building has been constructed as per the structural design furnished by the private chartered Engineer E.R. Vetrivel, M.Tech (Structural), F.I.V.,C.E.(I) I have come to an opinion that the building is structurally sound to be used as a public Building for the purpose specified in the statement. The structural soundness of the building has been verified taking into account the loading as per the latest Indian Standards 875. I am therefore of the opinion that a license may be granted for the period from **07.06.2022 to 06.06.2025**

STATEMENT TO ACCOMPANY THE OPINION REGARDING STRUCTURAL SOUNDNESS

Location of the Building (Door No. Street No. Name of the Place :	CARE International School, Door No. #27, SF.No.9/8, 9/9, 9/10, 8/2, A1G & 8/2 A1H Thayanur, Trichy					
	Built-up area	Age of the Building	Purpose for which the building can be used	The Period for which the building will be structurally sound	Number of persons to be accommodated	Remarks
Ground Floor including GI Sheet Roof	5626.41 Sq.m					
First Floor	2190.56 Sq.m					
Second Floor	2296.12 Sq.m	11 years	Education (School Building)	07.06.2022 to 06.06.2025	1050 Nos.	
Head Room	89.82 Sq.m					
Total	10202.91 Sq.m					

Superintending Engineer, PWD,
Buildings (C&M) Circle, Trichy-1.

[Signature]
18/8/2022